## **Uber** Carshare

## Owner's Service Form

DATE OF INSPECTION

Inspection		Pass	Fail	Insp	ection	Pass	Fail
1	BRAKES	0	0	7	LIGHTS	P	0
	Right front	9	0		Headlights		0
	Right rear	9	0		Turn indicator lights	9	0
	Left front	9	0		Brake lights	9	0
	Left rear	Ġ	0		Tail lights	De	0
	Handbrake	9	0			0	0
			_	8	DOORS (open, close, lock)	Q.	O
2	CLUTCH (manual only)	0	$-\Theta$	9	SPEEDOMETER	<b>*</b>	0
3	TYRES	0	0	ŭ	OI EEDOMETEK		
	Right front	9	0	10	WARNING LIGHTS	8	0
	Right rear	0				<b>50.</b>	0
	Left front	0	0	11	REAR VIEW MIRRORS	P	0
	Left rear	99	0	12	SEAT BELTS	X	0
					02/11 B22/0		
4	STEERING	9	0	13	AIRBAGS	X	0
5	SUSPENSION	9	0				
	Front	<b>\$</b>	0				
	Rear	9	0				
6	WINDSCREEN	*	0	TI	This car was inspected by the qualified mechanic listed below and satisfactorily		
	Large crack (+3cm)= Fail	8	0				
	Small crack (-3cm)= Pass	8	0		passes the checks listed on this form.		
	Front glass	0	0			PASS FA	
	Front wipers	9	0			PASS FAIL	
	Rear glass	9	0			8	
	Rear wiper (if available	Ø	0				
094/55 NISSAN TIDA 2013							
CAR REGO CAR MAKE CAR MODEL CAR YEAR							
FRIEDERICH SONTAG 152064							
INSPECTION COMPANY NAME ODO MILEAGE							
Friederich John						11. 202	3
The control						11. 10/	<u> </u>

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only representative of their opinions.